


Staveley and Copgrove P C

Play Area Inspection



Inspected by Park Lane Playgrounds



13th June 2018 at 11.00am



Unit: Wicksteed Whirly Bird
Year of Manufacture: 2000
Overall Condition: Good
Comments: Wet pour surface showing signs of wear
 Debris on the surface

Surfacing: (See Appendix A)
 Wetpour



Unit: Record Cradle Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments: Bird excrement on the seats and surface
 Crack in the wetpour surface

Surfacing: (See Appendix A)
 Wetpour



Unit: Record Flat Seat Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments: Bird excrement on the seats and the wetpour surface

Surfacing: (See Appendix A)
 Wetpour



Unit: Hags Multi Pondo
Year of Manufacture: 2000
Overall Condition: Good
Comments: Rubber missing on the footrest
 Damage to the rubber
 Debris and weeds on the surface

Surfacing: (See Appendix A)
 Wetpour




Unit: Play and Leisure Multi Unit
Year of Manufacture: 2000



Overall Condition: Good
Comments: Chains showing signs of wear
Debris and weeds on the surface

Surfacing: (See Appendix A)
Wetpour



Unit: Play and Leisure Fish Spring Mobile
Year of Manufacture: 2006
Overall Condition: Good
Comments:

Surfacing: Wetpour



Unit: Ledon Car Spring Mobile
Year of Manufacture: 2002
Overall Condition: Good
Comments:

Surfacing: Wetpour



Unit: Bench
Year of Manufacture: Unknown
Overall Condition: Good
Comments:

Surfacing: Rubber Grassmat



Unit: Goalposts
Year of Manufacture: Unknown
Overall Condition: Average
Comments: Moles hills on the area
Grass requires cutting
(See Appendix A)

Sufacing: Grass



Unit: Fencing and Gates
Year of Manufacture: Unknown
Overall condition: Average



Comments:

Drop Pin Missing on Vehicle Access Gate
1 no post loose in ground, moss on fence
and pedestrian gate.
No padlock on the vehicle access gate
(See Appendix A)

Appendix A

Whirley bird



Comments:

Wet pour showing signs of wear

Recommendations:

Monitor the wet pour until the next inspection



Comments:

Debris on the area

Recommendations:

Remove the debris



Comments:

Debris and grass on the surface

Recommendations:

Remove the grass and debris to prolong the life of
the wetpour

Cradle Swings



Comments:

Bird excrement on the seat and surface

Recommendations:

Remove the excrement





Comments:

Crack in the wet pour surface

Recommendations:

Monitor the crack until the next inspection

Flat Seat swings



Comments:

Bird excrement on the seats and surface

Recommendations:

Remove the excrement



Multi pondo



Comments:

Rubber footrest missing

Recommendations:

Replace the rubber



Comments:

rubber damaged

Recommendations:

Remove the rubber and replace



Comments:

Debris and grass on the surface

Recommendations:

Remove the debris and grass to prolong the life



of the wetpour surface

Multi Unit



Comments:

Chains showing signs of wear

Recommendation:

Monitor chains until next inspection



Comments:

Weeds and debris on the area

Recommendations:

Remove the debris and weeds



Fencing and Gates



Comments:

Drop pin missing on vehicular Access Gate
No Padlock

Recommendation:

Replace Drop pin
Replace the padlock



Comments:

1 no post loose in ground

Recommendation:

Secure loose post



Comments:

Moss on pedestrian gate and fencing

Recommendation:

Remove moss from fencing and gate



Comments:

Mole hills on the area

Recommendations:

Remove the mole hills



Comments:

Over grown grass

Recommendations:

Cut the grass inside and outside the area.

***The foregoing report is a true representation of the play area at the time of inspection.
The Inspection was entirely visual and no equipment was dismantled.***