

# Staveley and Copgrove P C

## Play Area Inspection



Inspected by Park Lane Playgrounds



1st March 2017 at 2.00PM



**Unit:** Wicksteed Whirly Bird  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Paintwork showing signs of wear  
Moss on safety surface  
**( See Appendix A )**  
**Surfacing:** Wetpour



**Unit:** Record Cradle Swings  
**Year of Manufacture:** Unknown  
**Overall Condition:** Good  
**Comments:** cable ties do not  
comply with BS EN1176 standards  
Moss on the seats and surface  
Lubricate the bushes and shackles  
**( See Appendix A )**  
**Surfacing:** Wetpour  
Crack in the wetpour monitor until the  
next inspection




**Unit:** Record Flat Seat Swings  
**Year of Manufacture:** Unknown  
**Overall Condition:** Good  
**Comments:** cable ties do not comply with  
BS EN1176 standards  
Moss and debris on the safety surface  
Mole hills around the edge of the surface  
**(See Appendix A)**  
**Surfacing:** Wetpour



**Unit:** Hags Multi Pondo  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Moss on the safety surface  
**Surfacing:** Wetpour



**Unit:** Play and Leisure Multi Unit  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Paint corrosion



Chains showing signs of wear

( See Appendix A)

Surfacing: Wetpour



Unit: Play and Leisure Fish Spring Mobile

Year of Manufacture:2006

Overall Condition: Good

Comments: Moss on the safety surface

Surfacing: Wetpour



Unit: Ledon Car Spring Mobile

Year of Manufacture:2002

Overall Condition: Good

Comments: Moss on safety surface, clamps showing signs of wear

(See Appendix A)

Surfacing: Wetpour



Unit: Bench

Year of Manufacture:Unknown

Overall Condition: Good

Comments:

Surfacing: Rubber Grassmat



Unit: Goalposts

Year of Manufacture:Unknown


Overall Condition: Average

Comments: Both goals slightly loose in ground-monitor until next inspection

Moles hills on the area

(See Appendix A)

Surfacing: Grass



Unit: Fencing and Gates

Year of Manufacture:Unknown

Overall condition: Average

Comments: Drop Pin Missing on Vehicle Access Gate  
1 no post loose in ground, moss on fence and pedestrian gate.



(See Appendix A)

## Appendix A

### Whirley bird



**Comments:**  
Paintwork showing signs of wear

**Recommendation:**  
Monitor until next inspection

### Cradle Swings



**Comments:**  
Cable ties do not comply with BS EN1176 standards

**Recommendation:**  
Monitor cable ties for any sharp edges



**Comments:**  
Moss on the safety surface

**Recommendations:**  
remove moss



**Comments:**  
Moss on the seats

**Recommendations:**  
Remove the moss so the swings can be used



**Comments:**  
Crack in the wet pour

**Recommendations:**  
Monitor the surface until the next inspection



**Comments:**



Mole hills around the edge of the surface

**Recommendations:**

Remove the mole hills

**Multi Unit**



**Comments:**

Paint corrosion

**Recommendation:**

Sand down and re-paint that complies with EN1176.4.1.1 standard.



**Comments:**

Chains showing signs of wear

**Recommendation:**

Monitor chains until next inspection



**Comments:**

Moss on the surface area

**Recommendations:**

Remove the moss

**Springers**



**Comments:**

Clamps showing signs of wear

**Recommendation:**

Monitor the clamps until the next inspection



**Comments:**

Moss on the surface

**Recommendations:**

Remove the moss

**Fencing and Gates**



**Comments:**

Drop pin missing on vehicular Access Gate



**Recommendation:**  
Replace Drop pin



**Comments:**  
1 no post loose in ground

**Recommendation:**  
Secure loose post



**Comments:**  
Moss on pedestrian gate and fencing

**Recommendation:**  
Remove moss from fencing and gate



**Comments:**  
Mole hills on the area

**Recommendations:**  
Remove the mole hills

***The foregoing report is a true representation of the play area at the time of inspection.  
The Inspection was entirely visual and no equipment was dismantled.***