

# Staveley and Copgrove P C

## Play Area Inspection



**Inspected by Park Lane Playgrounds**



**5th December 2016 at 2.50pm**



Unit: Wicksteed Whirly Bird  
 Year of Manufacture: 2000  
 Overall Condition: Good  
 Comments: Paintwork showing signs of wear  
 Moss on safety surface  
 ( See Appendix A)  
 Surfacing: Wetpour



Unit: Record Cradle Swings  
 Year of Manufacture: Unknown  
 Overall Condition: Good  
 Comments: cable ties do not  
 comply with BS EN1176 standards  
 Moss on the seats and surface  
 ( See Appendix A)  
 Surfacing: Wetpour




Unit: Record Flat Seat Swings  
 Year of Manufacture: Unknown  
 Overall Condition: Good  
 Comments: cable ties do not comply with  
 BS EN1176 standards  
 Moss on the safety surface  
 (See Appendix A)  
 Surfacing: Wetpour



Unit: Hags Multi Pondo  
 Year of Manufacture: 2000  
 Overall Condition: Good  
 Comments: Moss on the safety surface  
 Surfacing: Wetpour



Unit: Play and Leisure Multi Unit  
 Year of Manufacture: 2000  
 Overall Condition: Good  
 Comments: Paint corrosion



Chains showing signs of wear

( See Appendix A)

Surfacing:

Wetpour



Unit:

Play and Leisure Fish Spring Mobile

Year of Manufacture:2006

Overall Condition: Good

Comments: Moss on the safety surface

Surfacing:

Wetpour



Unit:

Ledon Car Spring Mobile

Year of Manufacture:2002

Overall Condition: Good

Comments: Moss on safety surface, clamps showing signs of wear

(See Appendix A)

Surfacing:

Wetpour



Unit:

Bench

Year of Manufacture:Unknown

Overall Condition: Good

Comments:

Surfacing:

Rubber Grassmat



Unit:

Goalposts

Year of Manufacture:Unknown

Overall Condition: Average


Comments: Both goals slightly loose in ground-monitor until next inspection

Moles hills on the area

(See Appendix A)

Surfacing:

Grass



Unit:

Fencing and Gates

Year of Manufacture:Unknown

Overall condition: Average

Comments: Drop Pin Missing on Vehicle Access Gate

1 no post loose in ground, moss on fence and pedestrian gate.





(See Appendix A)

## Appendix A

### Whirley bird



**Comments:**

Paintwork showing signs of wear

**Recommendation:**

Monitor until next inspection

### Cradle Swings



**Comments:**

Cable ties do not comply with BS EN1176 standards

**Recommendation:**

Monitor cable ties for any sharp edges



**Comments:**

Moss on the safety surface

**Recommendations:**

remove moss




**Comments:**

Moss on the seats

**Recommendations:**

Remove the moss so the swings can be used

### Multi Unit



**Comments:**

Paint corrosion

**Recommendation:**

Sand down and re-paint that complies with EN1176.4.1.1 standard.



**Comments:**  
Chains showing signs of wear

**Recommendation:**  
Monitor chains until next inspection



**Comments:**  
Moss on the surface area

**Recommendations:**  
Remove the moss

### Springers



**Comments:**  
Clamps showing signs of wear

**Recommendation:**  
Monitor the clamps until the next inspection



**Comments:**  
Moss on the surface

**Recommendations:**  
Remove the moss

### Fencing and Gates



**Comments:**  
Drop pin missing on vehicular Access Gate

**Recommendation:**  
Replace Drop pin



**Comments:**  
1 no post loose in ground

**Recommendation:**  
Secure loose post



**Comments:**  
Moss on pedestrian gate and fencing



**Recommendation:**

Remove moss from fencing and gate



**Comments:**

Mole hills on the area

**Recommendations:**

Remove the mole hills

***The foregoing report is a true representation of the play area at the time of inspection.  
The Inspection was entirely visual and no equipment was dismantled.***