

# Staveley and Copgrove P C

## Play Area Inspection



**Inspected by Park Lane Playgrounds**



**9th March 2016 3.45PM**





**Unit:** Wicksteed Whirly Bird  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Weed growth, moss and debris on area,  
 Paintwork showing signs of wear  
**( See Appendix A)**

**Surfacing:** Wetpour




**Unit:** Record Cradle Swings  
**Year of Manufacture:** Unknown  
**Overall Condition:** Good  
**Comments:** Bushes require lubricating, moss on seats,  
 moss and debris on area, cable ties do not  
 comply with BS EN1176 standards  
 There are several mole hills  
**( See Appendix A)**

**Surfacing:** Wetpour




**Unit:** Record Flat Seat Swings  
**Year of Manufacture:** Unknown  
**Overall Condition:** Good  
**Comments:** Bushes require lubricating, moss and debris  
 on area, cable ties do not comply with  
 BS EN1176 standards  
**(See Appendix A)**

**Surfacing:** Wetpour



**Unit:** Hags Multi Pondo  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Damage to safety surface, moss and debris  
 on area.  
**(See Appendix A)**

**Surfacing:** Wetpour



**Unit:** Play and Leisure Multi Unit  
**Year of Manufacture:** 2000  
**Overall Condition:** Good  
**Comments:** Paint corrosion, weed growth, moss and debris on safety surface.  
Chains showing signs of wear  
( See Appendix A)  
**Surfacing:** Wetpour



**Unit:** Play and Leisure Fish Spring Mobile  
**Year of Manufacture:** 2006  
**Overall Condition:** Good  
**Comments:** Moss and debris on safety surface.  
Clamps are showing signs of wear  
monitor until next inspection  
(See Appendix A)

**Surfacing:** Wetpour



**Unit:** Ledon Car Spring Mobile  
**Year of Manufacture:** 2002  
**Overall Condition:** Good  
**Comments:** Moss and debris on safety surface  
(See Appendix A)

**Surfacing:** Wetpour



**Unit:** Bench  
**Year of Manufacture:** Unknown  
**Overall Condition:** Good  
**Comments:** Weed growth under bench  
( See Appendix A)

**Surfacing:** Rubber Grassmat



**Unit:** Goalposts  
**Year of Manufacture:** Unknown  
**Overall Condition:** Average  
**Comments:** Both goals slightly loose in ground, mole hills in area.  
Re secure the clips as the net is not attached  
(See Appendix A)

**Surfacing:** Grass





**Unit:** Fencing and Gates  
**Year of Manufacture:** Unknown  
**Overall condition:** Average  
**Comments:** Drop Pin Missing on Vehicle Access Gate  
 1 no post loose in ground, moss on fence  
 and pedestrian gate.  
**(See Appendix A)**

## Appendix A

**Whirly Bird**



**Comments:**  
 Weed growth and moss and debris on area

**Recommendation:**  
 Remove weeds, moss and debris



**Comments:**  
 Paintwork showing signs of wear

**Recommendation:**  
 Monitor until next inspection

**Cradle Seat Swings**



**Comments:**  
 Moss on seats and bushes require lubricating

**Recommendation:**  
 Remove moss and lubricate bushes



**Comments:**  
 Moss and debris on area

**Recommendation:**  
 Remove moss and debris



**Comments:**

Cable ties do not comply with BS EN1176 standards

**Recommendation:**

Monitor cable ties for any sharp edges



**Comments:**

Mole hills

**Recommendations:**

remove mole hills as they are a trip hazard

**Flat Seat Swings**



**Comments:**

Moss and debris on area and bushes require lubricating.

**Recommendation:**

Remove moss and debris and lubricate bushes

**Multi Pondo**



**Comments:**

Damage to safety surface

**Recommendation:**

Monitor safety surface until next inspection



**Comments:**

Moss and debris on safety surface

**Recommendation:**

Remove moss and debris

**Multi Unit**



**Comments:**

Paint corrosion

**Recommendation:**

Sand down and re-paint that complies with EN1176.4.1.1 standard.



**Comments:**

Weed growth, moss and debris on safety surface

**Recommendation:**

Remove weeds, moss and debris



**Comments:**

Chains showing signs of wear

**Recommendation:**

Monitor chains until next inspection

**Springers**




**Comments:**

Moss and debris in springers safety surface

**Recommendation:**

Remove moss and debris



**Comments:**

Clamps showing signs of wear

**Recommendations:**

Monitor the clamps until the next inspection

**Goal Posts**



**Comments:**

2no goal post slightly loose in ground

**Recommendation:**

Monitor goals until next inspection



**Comments:**

the net is not attached

**Recommendations:**

Secure the net





**Comments:**

Mole hills in area

**Recommendation:**

Remove mole hills



**Comments:**

Drop pin missing on vehicular Access Gate

**Recommendation:**

Replace Drop pin



**Comments:**

1 no post loose in ground

**Recommendation:**

Secure loose post



**Comments:**

Moss on pedestrian gate and fencing

**Recommendation:**

Remove moss from fencing and gate

***The foregoing report is a true representation of the play area at the time of inspection.  
The Inspection was entirely visual and no equipment was dismantled.***