Staveley and Copgrove P C

Play Area Inspection



Inspected by Park Lane Playgrounds





6th June 2019 at 1.15pm





Year of Manufacture: 2000
Overall Condition: Good

Comments: Wet pour surface showing signs of wear

(See Appendix A)

Surfacing: Wetpour



Unit: Record Cradle Swings

Year of Manufacture: Unknown Overall Condition: Good

Comments: Grease the unit

(See Appendix A)

Surfacing: Wetpour



Unit: Record Flat Seat Swings

Year of Manufacture: Unknown Overall Condition: Good

Comments: Chains wearing monitor this until the next

inspection

Surfacing: Wetpour



Unit: Hags Multi Pondo

Year of Manufacture: 2000 Overall Condition: Good

Comments: 2no footrests missing

(See Appendix A)

Surfacing: Wetpour



Unit: Play and Leisure Multi Unit

Year of Manufacture: 2000
Overall Condition: Good

Comments: Chains showing signs of wear



Weeds and debris on the area

(See Appendix A)

Surfacing: Wetpour



Unit: Play and Leisure Fish Spring Mobile

Year of Manufacture: 2006
Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Ledon Car Spring Mobile

Year of Manufacture: 2002 Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Bench
Year of Manufacture: Unknown
Overall Condition: Good

Comments:

Surfacing: Rubber Grassmat



Unit: Goalposts
Year of Manufacture: Unknown
Overall Condition: Average

Comments:

Sufacing: Grass



Unit: Fencing and Gates

Year of Manufacture: Unknown
Overall condition: Average

Comments: Drop Pin Missing on Vehicle Access Gate

No padlock on the vehicle access gate

(See Appendix A)

The foregoing report is a true representation of the play area at the time of inspection. The Inspection was entirely visual and no equipment was dismantled.

Appendix A
Whirley bird



Comments:

Wet pour showing signs of wear

Recommendations:

Monitor the wet pour until the next inspection

Flat seat swings



Comments:

Slight wear on the chains

Recommendations:

Monitor the chains until the next inspection

Multi pondo



Comments:

Both footrest missing

Recommendations:

Replace the rubber

Multi Unit



Comments:

Chains showing signs of wear

Recommendation:

Monitor chains until next inspection



Comments:

Weeds and debris on the area

Recommendations:

Remove the debris and weeds

Area



Comments:

Debris on the area

Recommendations:

Remove all debris

Fencing and Gates



Comments:

Drop pin missing on vehicular Access Gate No Padlock

Recommendation:

Replace Drop pin Replace the padlock