

Staveley and Copgrove P C

Play Area Inspection



Inspected by Park Lane Playgrounds



5th June 2020 at 11.30am



Unit:

Wicksteed Whirly Bird



Year of Manufacture: 2000
Overall Condition: Good
Comments: Wet pour surface showing signs of wear

Surfacing: (See Appendix A)
Wetpour



Unit: Record Cradle Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments: Grease the unit
Chains showing signs of wear
debris on the area
wetpour surface has sunk

Surfacing: (See Appendix A)
Wetpour



Unit: Record Flat Seat Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments: Chains wearing monitor this until the next inspection
Debris on the area

Surfacing: (See Appendix A)
Wetpour



Unit: Hags Multi Pondo
Year of Manufacture: 2000
Overall Condition: Good
Comments: 2no footrests missing
Moss and debris on the area

Surfacing: (See Appendix A)
Wetpour



Unit: Play and Leisure Multi Unit
Year of Manufacture: 2000
Overall Condition: Good
Comments: Chains showing signs of wear



Surfacing:

Weeds and debris on the area
Moss on the safety surface
(See Appendix A)
Wetpour



Unit: Play and Leisure Fish Spring Mobile
Year of Manufacture: 2006
Overall Condition: Good
Comments:

Surfacing: Wetpour



Unit: Ledon Car Spring Mobile
Year of Manufacture: 2002
Overall Condition: Good
Comments:

Surfacing: Wetpour




Unit: Bench
Year of Manufacture: Unknown
Overall Condition: Good
Comments:

Surfacing: Rubber Grassmat



Unit: Goalposts
Year of Manufacture: Unknown
Overall Condition: Average
Comments: Mole hills on the field

(See Appendix A)
Surfacing: Grass



Unit: Fencing and Gates
Year of Manufacture: Unknown
Overall condition: Average
Comments: Drop Pin Missing on Vehicle Access Gate
No padlock on the vehicle access gate

(See Appendix A)

*The foregoing report is a true representation of the play area at the time of inspection.
The inspection was entirely visual and no equipment was dismantled.*

Appendix A

Whirley bird



Comments:

Wet pour showing signs of wear

Recommendations:

Monitor the wet pour until the next inspection



Comments:

Weeds on the area

Recommendations:

Remove the weeds to prolong the life of the wet pour surface

Cradle seats



Comments:

Chains showing signs of wear

Recommendations:

monitor the chain until the next inspection



Comments:

Grass encroaching on to the wet pour surface

Recommendations:

Remove the grass and debris to prolong the life of the surface



Comments:

Wetpour surface has sunk

Recommendations:

Monitor the wetpour surface until the next inspection

Flat seat swings



Comments:
Slight wear on the chains

Recommendations:
Monitor the chains until the next inspection



Comments:
Grass encroaching surface

Recommendations:
Remove the grass to prolong the life of the surface

Multi pondo



Comments:
Both footrest missing

Recommendations:
Replace the rubber

Multi Unit



Comments:
Chains showing signs of wear

Recommendation:
Monitor chains until next inspection



Comments:
Weeds and debris on the area

Recommendations:
Remove the debris and weeds





Area



Comments:

Debris and weeds on the area

Recommendations:

Remove all debris from the area, clear the site from moss and grass



Fencing and Gates




Comments:

Drop pin missing on vehicular Access Gate
No Padlock

Recommendation:

Replace Drop pin
Replace the padlock

Bin



Comments:

Bin is not secure

Recommendations:



Secure the bin



Comments:

Very sharp edges on the pig netting

Recommendations:

We would recommend using chain link fencing



Comments:

Broken rail

Recommendations:

Replace the rail or remove from site

Bin Leading to the park



Comments:

The bin is not secure

Recommendations:

Secure the bin



Comments:

Mole hills on the football pitch

Recommendations:

Remove the mole hills as they are a trip hazard

