

Staveley and Copgrove P C

Play Area Inspection



Inspected by Park Lane Playgrounds



5th March 2018 at 3.20PM



Unit:

Wicksteed Whirly Bird



Year of Manufacture: 2000
Overall Condition: Good
Comments: Mole hills around the area
Wet pour surface showing signs of wear
Debris on the surface
(See Appendix A)
Surfacing: Wetpour



Unit: Record Cradle Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments: Moss on the seats
(See Appendix A)
Surfacing: Wetpour



Unit: Record Flat Seat Swings
Year of Manufacture: Unknown
Overall Condition: Good
Comments:
Surfacing: Wetpour



Unit: Hags Multi Pondo
Year of Manufacture: 2000
Overall Condition: Good
Comments: Rubber missing on the footrest
(See Appendix A)
Surfacing: Wetpour



Unit: Play and Leisure Multi Unit
Year of Manufacture: 2000
Overall Condition: Good
Comments: Chains showing signs of wear



Surfacing:

Debris on the surface

(See Appendix A)

Wetpour



Unit:

Play and Leisure Fish Spring Mobile

Year of Manufacture: 2006

Overall Condition: Good

Comments:

Surfacing:

Wetpour



Unit:

Ledon Car Spring Mobile

Year of Manufacture: 2002

Overall Condition: Good

Comments:

Surfacing:

Wetpour



Unit:

Bench

Year of Manufacture: Unknown

Overall Condition: Good

Comments:

Surfacing:

Rubber Grassmat



Unit:

Goalposts

Year of Manufacture: Unknown


Overall Condition: Average

Comments: Moles hills on the area

Sufacing:

(See Appendix A)

Grass



Unit:

Fencing and Gates

Year of Manufacture: Unknown

Overall condition: Average

Comments: Drop Pin Missing on Vehicle Access Gate
1 no post loose in ground, moss on fence and pedestrian gate.
No padlock on the vehicle access gate

(See Appendix A)

Appendix A

Whirley bird



Comments:

Wet pour showing signs of wear

Recommendations:

Monitor the wet pour until the next inspection



Comments:

Debris on the area

Recommendations:

Remove the debris

Cradle Swings



Comments:

Moss on the seats

Recommendations:

Remove the moss so the swings can be used

Multi pondo




Comments:

Rubber footrest missing

Recommendations:

Replace the rubber

Multi Unit



Comments:

Chains showing signs of wear

Recommendation:

Monitor chains until next inspection

Fencing and Gates



Comments:

Drop pin missing on vehicular Access Gate
No Padlock

Recommendation:

Replace Drop pin
Replace the padlock



Comments:

1 no post loose in ground

Recommendation:

Secure loose post



Comments:

Moss on pedestrian gate and fencing

Recommendation:

Remove moss from fencing and gate



Comments:

Mole hills on the area

Recommendations:

Remove the mole hills



The foregoing report is a true representation of the play area at the time of inspection.

The Inspection was entirely visual and no equipment was dismantled.