Staveley and Copgrove P C

Play Area Inspection



Inspected by Park Lane Playgrounds





5th December 2017 at 2.00pm



Jnit: Wicksteed Whirly Bird

Year of Manufacture:2000 **Overall Condition:** Good

Comments: Mole hills around the area

Wet pour surface showing signs of wear

(See Appendix A)

Surfacing: Wetpour



Unit: Record Cradle Swings

Year of Manufacture: Unknown
Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Record Flat Seat Swings

Year of Manufacture:Unknown
Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Hags Multi Pondo

Year of Manufacture:2000 Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Play and Leisure Multi Unit

Year of Manufacture:2000 Overall Condition: Good

Comments: Chains showing signs of wear



(See Appendix A)

Surfacing: Wetpour



Unit: Play and Leisure Fish Spring Mobile

Year of Manufacture:2006

Overall Condition: Good

Comments:

Surfacing: Wetpour



Unit: Ledon Car Spring Mobile

fear of Manufacture:2002

Overall Condition: Good

comments:

urfacing: Wetpour



Jnit: Bench
/ear of Manufacture:Unknown
Dverall Condition: Good

Comments:

urfacing: Rubber Grassmat



Jnit: Goalposts
/ear of Manufacture:Unknown
Dverall Condition: Average

omments: Moles hills on the area

(See Appendix A)

ufacing: Grass



Unit: Fencing and Gates

Year of Manufacture: Unknown Overall condition: Average

Comments: Drop Pin Missing on Vehicle Access Gate

1 no post loose in ground, moss on fence

and pedestrian gate. (See Appendix A)

Appendix A

Whirley bird



Comments:

Wet pour showing signs of wear

Recommendations:

Monitor the wet pour until the next inspection

Cradle Swings



Comments:

Moss on the seats

Recommendations:

Remove the moss so the swings can be used

Multi Unit



Comments:

Chains showing signs of wear

Recommendation:

Monitor chains until next inspection

Fencing and Gates



Comments:

Drop pin missing on vehicular Access Gate

Recommendation:

Replace Drop pin



Comments:

1 no post loose in ground

Recommendation:

Secure loose post



Comments:



Moss on pedestrian gate and fencing

Recommendation:

Remove moss from fencing and gate

Comments:

Mole hills on the area

Recommendations:

Remove the mole hills

The foregoing report is a true representation of the play area at the time of inspection. The Inspection was entirely visual and no equipment was dismantled.