

6. Springy Car

Function	Correct
Structure	Sound
Caps	Correct, none missing
Safety Surface	Sound

7. See-saw

Operation	Correct may need lubrication
Structure	Sound
Paint	Flaking off Priority 3
Tyres	Sound
Caps	Correct, none missing
Safety Surface	Sound

8. Swings (SE3674362493)

Operation	Sound
Structure	Sound
Seats	Sound Bird excrement present Priority 1
Chains	Sound
Fixings	Sound & secure
Safety Surface	Sound

9. Baby Swings (SE3674362507)

Operation	Sound
Structure	Sound
Seats	Sound some Lichen present Priority 3
Chains	Sound
Fixings	Sound & Secure
Safety Surface	Cavity below surface Priority 2

10. Roundabout

Operation	Sound
Structure	Sound
Seats	Sound
Paint	Heavily Chipped Priority 3
Safety Surface	Sound

11. Central Climbing Structure

Structure	Sound
Chains	Sound
Paint	Flaking Priority 3
Safety Surface	Sound

12 Southern Goalpost

Structure	Sound
Paint	Poor

13. Northern Goalpost

Structure	Sound
Paint	Poor