

## **6. Springy Car**

Function	Correct
Structure	Sound
Caps	Correct, none missing
Safety Surface	Sound

## **7. See-saw**

Operation	Correct may need lubrication
Structure	Sound
Paint	Flaking off Priority 3
Tyres	Sound
Caps	Correct, none missing
Safety Surface	Sound

## **8. Swings (SE3674362493)**

Operation	Sound
Structure	Sound
Seats	Sound Bird excrement present Priority 1
Chains	Sound
Fixings	Sound & secure
Safety Surface	Sound

## **9. Baby Swings (SE3674362507)**

Operation	Sound
Structure	Sound
Seats	Sound some Lichen present Priority 3
Chains	Sound
Fixings	Sound & Secure
Safety Surface	Cavity below surface Priority 2

## **10. Roundabout**

Operation	Sound
Structure	Sound
Seats	Sound
Paint	Heavily Chipped Priority 3
Safety Surface	Sound

## **11. Central Climbing Structure**

Structure	Sound
Chains	Sound
Paint	Flaking Priority 3
Safety Surface	Sound

## **12 Southern Goalpost**

Structure	Sound
Paint	Poor

## **13. Northern Goalpost**

Structure	Sound
Paint	Poor