

Grounds Maintenance and Forestry Contractors

Playground Inspection

Job No: STP/2/014

Site: Jubilee Recreation Field, HG5 9JX

What 3 words Location: Flagpole, Insurers, Agent GPS Located: SE3674462584

Date: 13 October 2021

Time: 10:41

Inspectors: T. Harris

Works Priority Schedule

Priority 1 - Immediate attention required

Priority 2 - Works required within a two month period

Priority 3 - Works required at some point

Site.

Site Integrity: Fencing secure and safe.

Gates functioning correctly and fastening.

No excrement.

No sharps found.

Signage (4 No) legible and secure

Tarmac footpath Minor cracking

Mole activity,, tripping hazard Priority 2

Trees. 1 No Cherry over Play Area deadwood, 1 No perimeter Ash with major compromised branch 1 No Ash major deadwood Priority 2

1. Bin (Entrance)

Mounting Sound

Capacity Empty

2. Bin (Mid Field)

Structure Sound

Capacity Empty

3. Bin (Play Area Fence)

Mounting Sound

Capacity Empty

4. Picnic Table

Structure Sound

Paint Sound

5. Springy Fish

Function Correct

Structure Sound

Caps Correct, none missing

Safety Surface Sound